

Introduction

Thank you for your interest in the Xilinx Virtex™-4 family of FPGAs. We are pleased to provide to you engineering samples of the Virtex-4 XC4VLX160CES and XC4VLX200CES devices. Although Xilinx has made every effort to ensure the highest possible quality, these devices are subject to the limitations described in this errata notice.

Devices

These errata apply to the XC4VLX160CES and XC4VLX200CES devices as shown in [Table 1](#).

Table 1: XC4VLX160 and XC4VLX200 Devices Affected by These Errata

Devices	XC4VLX160CES	JTAG ID (Revision Code): 0, 3
	XC4VLX200CES	JTAG ID (Revision Code): 0, 3
Packages	All	
Speed Grades	All	

Hardware Errata Details

This section provides a detailed description of each hardware issue known at the release time of this document.

FIFO16

The FIFO16 does not correctly generate the ALMOST EMPTY, EMPTY, ALMOST FULL, and FULL flags after the following sequence occurs:

1. Read or Write has reached the threshold value of ALMOST EMPTY OFFSET or ALMOST FULL OFFSET.
2. A single Read or Write operation is performed, followed by a simultaneous Read or Write operation, when active Read and Write clock edges are very close together.

Unexpected or corrupt data can occur as a result of the flag failures, even if the ALMOST EMPTY or ALMOST FULL flags are not being used.

This issue does not happen in FIFO16 applications where Read and Write never occur simultaneously. Workarounds (downloadable macros) are available for users who are performing simultaneous Read/Writes. Not all workarounds will achieve data sheet performance. See Xilinx answer record 22462 for more details, workaround solutions, and corresponding performance information.

Operational Guidelines

Design Software Requirements

The devices covered by these errata, unless otherwise specified, require the following Xilinx development software installations.

- Speed specification v1.57 (or later) and Xilinx software ISE 7.1i Service Pack 4 (SP4) or later is required when designing for the devices covered by this errata. Contact Xilinx technical support for SP4 help. Updates are available on the following web page:

http://www.xilinx.com/xlnx/xil_sw_updates_home.jsp

The stepping should be set to "1" in the constraint file (UCF file):

```
CONFIG STEPPING = "1";
```

- A summary list of ISE software known issues pertaining to the Virtex-4 features is available at:
http://support.xilinx.com/xlnx/xil_ans_display.jsp?iLanguageID=1&iCountryID=1&getPagePath=19713

Notes and Recommendations

Virtex-II and Virtex-II Pro FPGA Designers

For Virtex-II and Virtex-II Pro designers, the CCLK specification in Virtex-4 devices was changed to LVCMOS 12mA Fast slew rate. Xilinx recommends designing to this new standard.

Traceability

The XC4VLX200CES is marked as shown in Figure 1. The other devices listed in Table 1 are marked similarly.




Figure 1: Example XC4VLX200CES Package Marking

Additional Questions or Clarifications

All other device functionality and timing meet the data sheet specifications.

For additional questions regarding these errata, please contact your Xilinx Technical Support:
<http://www.xilinx.com/support/clearxpress/websupport.htm> or your Xilinx Sales Representative:
<http://www.xilinx.com/company/contact.htm>.

Obtaining the Most Recent Errata Version

If this document is printed or saved locally in electronic form, check for the most recent release, available to registered users on the Xilinx website at: http://www.xilinx.com/xlnx/xweb/xil_publications_index.jsp?category=Errata.

To receive an e-mail alert when this document changes, sign up at:
http://www.xilinx.com/xlnx/xil_ans_display.jsp?getPagePath=18815.

These errata apply to the following Virtex-4 documents:

Virtex-4 Overview (<http://www.xilinx.com/bvdocs/publications/ds112.pdf>)

Virtex-4 Data Sheet (<http://www.xilinx.com/bvdocs/publications/ds302.pdf>)

Virtex-4 User Guide (http://www.xilinx.com/bvdocs/user_guides/ug070.pdf)

XtremeDSP™ Design Guide (http://www.xilinx.com/bvdocs/user_guides/ug073.pdf)

Virtex-4 Configuration Guide (http://www.xilinx.com/bvdocs/user_guides/ug071.pdf)

Virtex-4 Packaging Guide (http://www.xilinx.com/bvdocs/user_guides/ug075.pdf)

Revision History

Date	Version	Description
04/08/05	1.0	Initial release.
10/04/05	1.1	Added XC4VLX160ES devices. Revised order of information on pages. Changed the Design Software Requirements to require speed specification 1.57 and ISE7.1i (SP4) software.
02/15/06	1.2	Added the FIFO16 section. Added JTAG ID. Updated Design Software Requirements section. Added to the Hardware Errata Details section. Changed configuration stepping from "ES" to "1." Replaced the LVTTTL I/O standard with LVCMOS I/O standard in the Notes and Recommendations section. Removed System Monitor errata because it is no longer in the Virtex-4 data sheet.