

Test Procedure for the NCP3125 Ceramic Evaluation Board




Figure 1: Test Setup

The following steps describe the test procedure for all these boards:

Suggested Equipment:

Current limited DC Power Supply (e.g. AGILENT 6645A)	1pc
DC Volt-Meter able to measure up to 60 V DC (e.g. KEITHLEY 2000)	2pcs
DC Amp-Meter able to measure up to 1 A DC (e.g. KEITHLEY 2000)	1pc
DC Amp-Meter able to measure up to 5 A DC (e.g. FLUKE 89 IV)	1pc
DC Electronic Load (e.g. AGILENT 6060B)	1pc

01/19/2010 -1- www.onsemi.com

Test Procedure:

- 1. Connect the test setup as shown in Figure 1.
- 2. Apply an input voltage, $V_{IN} = 4.5-13.2 \text{ Vdc}$
- 3. Apply Iout(load) = 0 A
- 4. Check that Vout = 2.5 Vdc
- 5. Set Iout to desired level 0 A- 4 A
- 6. Check that Vout = 2.5 Vdc
- 7. Turn off the load
- 8. Turn off V_{IN}
- 9. End of the test